April 10, 2020 UNIVERSITY OF COLORADO DENVER LYNX CROSSING RESIDENCE HALL RENOVATION hord coplan macht

00



Introductions Project Introduction Project Scope Questions & Discussion





PROJECT TEAM







JERED MINTER

CU Denver Campus Architect

CU Denver | Anschutz Medical Campus Project Manager

BEN BOHMANN

GWEN GILLEY

Hord Coplan Macht Principal in Charge



JASON BENTLEY Hord Coplan Macht **Project Manager**

Walnut St PROJECT INTRODUCTION



PROJECT INTRODUCTION



CENTRAL LOCATION

Carlos and the second summer and


3






SURROUNDING DEVELOPMENTS








TRANSPORTATION LINKS





PROJECT GOALS





INTERIOR PROJECT SCOPE









SITE CONTEXT

COLFAX AVENUE

WALNUT STREET

PARKING GARAGE

AURARIA PKWY

LYNX CROSSING

- Louise

1-25 NON RAMP

-

1-25 SON RAMP

1-25

NORTH

ENTRY

ATH STREE



STREET

EXTERIOR SCOPE

125

UNIVERSITY OF COLORADO DENVER SIGN LOCATION OPTIONS

AURARIA PKWY RESURFACE 5TH FLOOR ROOF AMAZON LOCKERS

ENTRY

ITH STREE

SECURE PARKING ACCESS

COURTYARD WOOD DECKING

LYNX ROSSING

CEMENT BOARD REPLACEMENT





LYNX CROSSING SIGN

STORM WATER CONTROL

> ADA PARKING


RESURFACE PARKING LOT





DISTANCES	LETTER HEIGHT
100ft	12"
150ft	15"
200ft	20"
250ft	25"
300ft	30"
700ft	70"

SIGNAGE – LYNX CROSSING




Replace 'CAMPUS VILLAGE' sign with 'LYNX CROSSING' Sign Potentially replace temporary 'CAMPUS VILLAGE' Banner

Potentially replace 'CAMPUS VILLAGE' Window Graphic adjacent to Main Entry

SIGNAGE - CU DENVER







SIGNAGE – NORTH ELEVATION



'CU UNIVERSITY OF COLORADO DENVER' Signage – Analyze location options

View from Auraria Parkway (on-ramp to I-25)


SIGNAGE – WEST ELEVATION



'CU UNIVERSITY OF COLORADO DENVER' Signage – Analyze location options

View from Auraria Parkway (off-ramp from I-25 northbound)

SIGNAGE – SOUTH ELEVATION



CEMENT BOARD REPLACEMENT




Cement board panels at West elevation




Cement board panels at east elevation

ADA SIGNAGE & PARKING




Re-sign as "Accessible Route"





Replace wood decking



Improve stormwater drainage


COURTYARD CANOPY



Potential replacement of weathered wood trim at courtyard canopy



AMAZON LOCKER LOCATION





Potential Amazon locker location outside secure area

DRB REVIEW ITEMS

25

UNIVERSITY OF COLORADO DENVER SIGN LOCATION OPTIONS

ENTRY

LYNX ROSSING

MENT BOARD REPLACEMENT MATERIAL



AMAZON LOCKER LOCATION

LYNX CROSSING SIGN

QUESTIONS AND DISCUSSION